

## ***Change Log on Firmware Aug 21st***

**1. TimeSlot Issue** - Time Slot Off does not exist anymore (Choice is ON, TS1 and TS2)

**2. New Programmable Function Key.** (Menu, Up, Down, Back, A/B DQT/QT, Volume, VFO has been added)

**3. Display full ham contact info.** -**Ham Contact works full screen now.** (With Callsign and First Name on same line.)

**4. Timezone Select - daylight savings etc. If GPS is enable and Time is set to use GPS time the Radio time is 1 hour behind**

Well our friend DO9PH found that it was in the original FW

Look at "Appendix/GPS/Calibrator/Manual" there you can set manually your time zone.

**5. Power on Logo has been corrected with a space in Power On.**